Tear off along this line to open.

PERFORATION HERE

PERFORATION DOTTED LINE DOES NOT PRINT

PRINT 2 COLOR
Black & White

BLACK INK FOR PRINTING IN BLACK AREAS

WHITE INK FOR PRINTING IN GRAY AREAS

1. Strip approximately 1.50” of cable jacket and separate wires.



2. Choose between TIA 568-A or TIA 568-B wiring configuration.

TIA 568-A



TIA 568-B



3. Sort wires and place into the IDC.
Note: For maximum performance, minimize the untwisting of individual pairs to 0.125”



4. Terminate wires using a Punch-Down Tool.